



## RAHA SADR INDUSTRIAL CO

### Specification of RAHA Natural Rubber

Parameter	Unit	SMR CV50	SMR CV60	SMR L	SMR 5	SMR GP	SMR 10	SMR 10CV	SMR 20	SMR 20CV
Dirt (max)	%wt	0.02	0.02	0.02	0.05	0.08	0.08	0.08	0.16	0.16
Ash (max)	%wt	0.50	0.50	0.50	0.60	0.75	0.75	0.75	1.00	1.00
Nitrogen (max)	%wt	0.60	0.60	0.60	0.60	0.60	0.60	0.60	0.60	0.60
Volatile Matter (max)	%wt	0.80	0.80	0.50	0.80	0.80	0.80	0.80	0.80	0.80
Po (min)		NA	NA	35	30	NA	30	NA	30	NA
PRI Index (min)		60	60	60	60	50	50	50	40	40
Lovibond Color: individual value (max)		NA	NA	6.0	NA	NA	NA	NA	NA	NA
Lovibond Color: range (max)		NA	NA	2.0	NA	NA	NA	NA	NA	NA
Mooney Viscosity (ML, 1+4, 100°C)		50 +/- 5	60 +/- 5	NA	NA	65 +/- 5	NA	60 +/- 5	NA	65 +/- 5



Unit303,Navab Complex,  
Navab Safavi St.,Esfahan-Iran



+983132355207  
+983132355214



info@rahaoil.com



www.rahaoil.com