



RAHA SADR INDUSTRIAL CO

Specification of RAHA Oil Sulfur

NO.	TEST	METHOD	Test Method
1	PURITY (ON DRY BASIC) (WT%) MIN	99.50	BS-4113
2	Ash Content(WT%)MAX	0.05	BS-4113
3	MOISTURE (WT%)MAX	0.5	BS-4113
4	HYDROCARBONS(WT%)MAX	0.05	BS-4113
5	ACIDITY (AS H ₂ SO ₄) (WT%)	MAX 0.02	ISO 3704
6	BULK DENSITY Kg/M ³	MAX 1240	ASTM D-1895
7	Color	BRIGHT YELLOW	VISUAL
8	MESH SIZE 2-6 MM	MIN 90%	ISO 8397
9	MESH SIZE >6.0 MM	MAX 10%	ISO 8397
10	MESH SIZE <2.0 MM	MAX 10 %	ISO 8397



Unit303,Navab Complex,
Navab Safavi St.,Esfahan-Iran



+983132355207
+983132355214



info@rahaoil.com



www.rahaoil.com